

TECHNICAL INFORMATION

TYPE NO FB/IN/ES 5100	TYPE Freshbrew/Instant/Esspresso	T.I.-NO FB/IN/ES 03/01				
SERIAL NUMBERS AFFECTED From machine no. 499137	ISSUED BY Documentation/ Wittenborg Odense					
SUBJECT Ingredient table	ISSUED FOR (X): <table border="1"> <tr> <td>Action</td> <td>X</td> </tr> <tr> <td>Information</td> <td>X</td> </tr> </table>		Action	X	Information	X
Action	X					
Information	X					

COMPONENTS CONCERNED

Omitted:

39582300 Grid

New:

39582300 Cable guides

MODIFICATION:

- Grid 39582300 has been removed
- Three new cable guides 39582300 have been introduced

REASON:

- The grid has been removed to improve exhausting of vapours from the mixing funnels. In order to avoid the harness to block the fan, the harness has been fixed with three new cable guides. See illustration below.



CONTACT PERSON:

- Bent Erik Truelsegaard

27.02.01 DATE :	Charlotte Schreiner PRODUCED BY :	27.02.01 DATE :	Bent Erik Truelsegaard CHECKED BY :
--------------------	--------------------------------------	--------------------	--